



INSTRUMENTS

Wiring Instructions for: Programmable Loop Powered LED Display - Type: TCX-LPI


Step 1: Unscrew window cover.....



Step 2: Remove display, keeping all wires intact.....




Step 3: Unplug green connector from display.....



Step 4: Feed into head and attach your loop + and - wires to the.....
unused + and - terminals on the green plug. (there is a wiring
diagram directly below the green plug on the display back,
for your reference)



Step 5: Reconnect green plug.....



Step 6: Reassemble.....

